CORNER RECORD

Agency Index Document Number 20210006

BK 23, PG 47

OF CORNER RECORDS PAGE 47

City of	Rocklin	County of _	Placer	, California
Brief Legal Description Radius point, Antelope Court, Antelope Oaks Unit No. 1, Bk. L of Maps, Pg. 86				
Sec. 18 CORNER TYPE		NER TYPE	COORDINATES (Optional) N. E.	
T. 11 N., R. 7 E., M.D.E	Government (Meander Rancho Date of Survey 3.&M.	Corner Control Property Other November 5, 2020	Elevation	e §§8801-8819
PLS Act Ref.:	8765(d)	X 8771	8773 Other:	
Corner/ Monument:	Left as found Found and tagged	Established Reestablished		onstruction onstruction
Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): Replaced original found monument per C.R. 23/36 on 11/05/2020 with countersunk survey spike and washer stamped LS 5914 based upon the ties established per C.R. 23/36 after the original monument was destroyed as a result of construction.				
SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on February 5, 2021 Signed P.L.S. or R.C.E. No. 1914 COUNTY SURVEYOR'S STATEMENT SURVEYOR'S STATEMENT				
This Corner Record was and examined and filed Signed Title County Surveyor's County Surveyor County Surveyor's County Surveyor's County Surveyor's County Su	FEBRUARY Banks Hy Co. Surv	22,2021 1 26,2021 P.L.S. Dr R.C.E. No.	8373 8373 No. EXP. 12.	BAROLLENOR 8373 W.S.C21

